




A	B	C1	C2	C3	PCS
1	10.001	768	448	55	1
2	10.002	973	308	55	1
3.1	10.301	386	126	16	1
3.2	10.302	350	140	16	1
3.3	10.303	350	140	16	1
3.4	10.304	396	355	3	1
3.5	10.305	448	200	16	1
4	10.007	800	380	16	1
5	10.008	800	40	20	1
6	10.009	800	400	22	1
7	10.010	1004	380	16	1
8	10.011	1004	380	16	1
9	10.012	1004	56	16	1
10	10.013	1004	345	16	1
11	10.014	322	324	16	4
12	10.015	424	324	16	3
13	10.016	1014	336	3	1
14	10.017	1014	438	3	1
15	10.018	426	361	16	1
































max.



max.




















max.



1

§2



2








8x $\phi 15 \times 12 \text{ mm}$ **r1**

4x $\text{Ø}8 \times 30 \text{ mm}$ **f1**


16x $\phi 4 \times 16 \text{ mm}$ **p19**

13x $20/11$ **r42**


4x **k16**




3




4



5





6



7 

4x  $\phi 7 \times 70 \text{ mm}$ **e27**


1x  **z1**




8 





18x  **I2**

5x  **n108**
 $20 \times 13 \times 3,5 \text{ mm}$

5x  **p55**
 $\phi 3 \times 20 \text{ mm}$



I  **A=B**





9

§2

10x  $\phi 4 \times 16$ mm **p19**





3x  **a1**

2x  **a2**

2x  **c18**


4x  M4x25 mm **j8**

4x  $\phi 8 \times 1,8$ mm **o21**



10

§2






2x  **c18**

4x  $\phi 15 \times 12$ mm **r1**

4x  20/11 **r42**

2x  M4x25 mm **j8**

2x  $\phi 8 \times 1,8$ mm **o21**




11







4x $\phi 7 \times 50$ mm **e1**

5x $\phi 3 \times 20$ mm **p55**

x5 **n109**








12



13

21x
ø16
s2

10x
Ø 15mm
s59



14







§18

1x
φ5x60 mm
p17

1x
φ10x50 mm
f35

1x
75x30x15/1,5mm
n14

2x
φ4x16 mm
p19



15

2x 
φ3x16 mm p20

